

# Repairs and Replacement Cost Estimate

Document No.:

RR-2024-001

Date:

June 14, 2024

Property Address:

123 Main Street, Springfield, USA

Prepared By:

John Doe, Senior Estimator

## ESTIMATE DETAILS

No.	Item Description	Unit	Quantity	Unit Cost (\$)	Total Cost (\$)
1	Replace Broken Window Glass	sq.ft.	10	25.00	250.00
2	Repair Roof Leak - Patch Area	sq.ft.	15	30.00	450.00
3	Replace Damaged Door	each	2	150.00	300.00
4	Paint Repair Area	sq.ft.	25	5.00	125.00
Subtotal					1,125.00
Contingency (5%)					56.25
Total Estimate					1,181.25

## IMPORTANT NOTES

- This document is an estimate only; actual costs may vary.
- All unit prices are based on current market rates and standard materials.
- Site inspection is recommended to confirm the extent of repairs needed.
- Estimate excludes unforeseen structural issues and regulatory fees.
- Validity of this estimate is 30 days from the date of issue.