

# Corrective Maintenance Work Order

Work Order No.	CM-2024-0054	Date Issued	2024-06-19
Requested By	John Doe	Department	Manufacturing
Asset/Equipment	Conveyor Belt A21	Asset ID	CB-A21
Location	Production Floor 2		

## Problem Description

Intermittent stops during operation, suspected sensor malfunction.
--

## Corrective Actions Taken

<ul style="list-style-type: none"><li>- Inspected conveyor</li><li>- Replaced faulty proximity sensor</li><li>- Tested operation to confirm resolution</li></ul>
--

## Parts & Materials Used

Part/Material	Quantity	Remarks
Proximity Sensor, PXS-09	1	Replaced
Cable ties	5	Secured wiring

## Personnel

Name	Signature	Date
Alex Smith	_____	2024-06-19
Maria Lee	_____	2024-06-19

## Completion

Date Completed	2024-06-19	Time Completed	15:45
Verified By	Michael Tan	Signature	_____

## Important Notes:

- All corrective actions must be documented for traceability and future reference.
- Ensure that replaced parts and test results are clearly recorded.
- Obtain appropriate signatures for accountability and verification.
- File this document in accordance with maintenance record-keeping policies.