

# Appendix A: Photographic Evidence

Date: 2024-06-14

Project/Site: ABC Construction Site

Prepared by: John Doe

## Overview

This appendix contains photographic evidence collected to document site conditions, completed works, and/or identified issues as part of the project documentation requirements. Each image includes a caption detailing description, location, and relevant notes.

## Photographs

Photo 1

**Photo 1:** North wall foundation, poured concrete.

*Location:* North perimeter

*Date:* 2024-06-12

Photo 2

**Photo 2:** Installed electrical conduit prior to backfill.

*Location:* East trench

*Date:* 2024-06-13

Photo 3

**Photo 3:** Water seepage observed at basement corner.

*Location:* Basement SW corner

*Date:* 2024-06-13

## Important Notes

- All photographs should be time stamped and labeled clearly for reference.
- Ensure images are unaltered and accurately represent the documented condition or issue.
- Retain original image files for verification if requested.
- Include relevant information (location, date, description) in each caption.
- Use photographs as supplementary evidence; written explanations should also be provided in the main report.