

# HVAC Maintenance Service Repair Receipt

Receipt No.	SRR-00123	Date	2024-06-15
Customer Name	John Doe	Phone	+1 555-0101
Address	123 Maple Drive, Springfield, IL 62704		

## SERVICE DETAILS

Description	Qty	Unit Price	Total
HVAC System Inspection	1	\$60.00	\$60.00
Filter Replacement	2	\$15.00	\$30.00
Thermostat Calibration	1	\$25.00	\$25.00

Subtotal	\$115.00
Tax (7%)	\$8.05
Total Amount	<b>\$123.05</b>
Payment Method	Credit Card

## TECHNICIAN REMARKS

System operating within normal parameters. All filters replaced. Customer advised on regular maintenance schedule.

Technician Signature

Customer Signature

## IMPORTANT NOTES

- Keep this receipt as proof of service and for warranty purposes.
- Ensure payment details are accurate before acknowledging receipt.
- Details of work performed and parts replaced must be clearly specified.
- Contact the service provider within 7 days in case of any discrepancies.
- HVAC systems require periodic maintenance for optimal performance and efficiency.