

Industrial Equipment Repair Receipt

Receipt No: 025199

Date Issued: 2024-06-20

Company Name: Apex Industrial Solutions

Address: 123 Machinery Rd, Industry City, ST 45300

Customer Name: John Smith

Contact: john.smith@company.com

Phone: +1-555-987-1234

EQUIPMENT DETAILS

EQUIPMENT	MODEL/SERIAL	DATE RECEIVED	REPORTED ISSUE
Hydraulic Press	HP900 / SN:9921X5	2024-06-18	No pressure build-up

REPAIR DETAILS

DESCRIPTION OF WORK PERFORMED	PARTS REPLACED	LABOR (HOURS)	COST
Disassembled and diagnosed faulty valve. Replaced hydraulic control valve. Tested system performance.	Control Valve, Seals	4	\$350.00

SUMMARY

PARTS TOTAL	LABOR TOTAL	OTHER CHARGES	TOTAL AMOUNT	PAYMENT STATUS
\$180.00	\$160.00	\$10.00	\$350.00	Paid

Customer Signature

Date: _____
Authorized Technician

Date: _____

IMPORTANT NOTES

- This receipt acknowledges completion of listed repairs on the specified equipment.
- Warranty on repairs and replaced parts may vary; please consult terms provided by the technician.
- Retain this document for future reference and warranty claims.
- Contact the service provider promptly if any issues persist post-repair.